



# **OPERATION AND MAINTENANCE MANUAL**

- **BSD-1000**
  
- **BSD-1200**

**LOW VOLTAGE  
METAL ASSEMBLY SCREWDRIVER**

**KILEWS INDUSTRIAL CO., LTD.**

<http://www.kilews.com>

Y20028-4-001



**NOTICE**

Metal Assembly Screwdrivers are designed for installing threaded fasteners in light industrial and appliance manufacturing applications.

KILEWS is not responsible for customer modification of tools for applications on which KILEWS was not consulted.

**WARNING****Important safety information enclosed.**

Read all these instructions before placing tool in service or operation this tool and save these instructions. It is the responsibility of the employer to place the information in this manual into the hands of the operator. Failure to observe the following warnings could result in injury. When using electric tools, Basic safety precautions should always be followed to reduce the risk of fire, electric shock and personal injury, including the following:

## **1. General Safety Rules**

## **2. Operations Cautions**

## **3. Specifications**

## **4. Description Of Operation**

## **5. Torque Adjustment Operation**

## **6. Accessories**

## **7. Servicing**

# 1. General Safety Rules

**WARNING!** Read all instructions Failure to follow all instructions listed below may result in electric shock fire and/or serious injure. The term “power tool” in all of the warning listed below refer to your mains operated (corded) power tool or battery operated (cordless) power tool.

## SAVE THESE INSTRUCTIONS

### 1) Electrical Safety

- a) **Keep work area clean and well lit.** Cluttered and dark areas invite accidents.
- b) **Do not operate power tools in explosive atmosphere, such as in the presence of flammable liquids, gases or dust.** Power tools creat sparks which may ignite the dust of fumes..
- c) **Keep children, and bystanders away while operating a power tool.** Distractions can cause you to lose control.

### 2) Electrical Safety

- a) **Power tool plugs must match the outlet. Never modify the plug in any way. Do not use any adapter plugs with earthed (grounded) power tools.** Unmodified plugs and matching outlets will reduce risk of electric shock.
- b) **Avoid body contact with earthed or grounded surfaces such as pipes, radiators, ranges and refrigerators.** There is an increased risk of electric shock if your body is earthed or grounded.
- c) **Don’t expose power tools to rain or wet conditions.** Water entering a power tool will increase the risk of electric shock.
- d) **Do not abuse the cord. Never use the cord to carrying, pulling or unplugging the power tool. Keep cord away from heat, oil, sharp edges or moving parts.** Damaged or entangled cords increase the risk of electric shock.
- e) **When operating a power tool outdoors, use an extension cord suitable for outdoor use.** Use of cord suitable for outdoor use reduces the risk of electric shock .

### 3) Personal Safety

- a) **Stay alert, watch what you are doing and use common sense when operating a power tool. Do not use power tool while you are tired or under the influence of drugs, alcohol, or medication.** A moment of inattention while operating power tools may result in serious personal injury.
- b) **Use safety equipment. Always wear eye protection.** Safety equipment such as dust mask, non-skid safety shoes, hard hat, or hearing protection used for appropriate conditions will reduce personal injuries.
- c) **Avoid accidental starting. Ensure the switch is in the off position before plugging in.** Carrying power tools with your finger on the switch or plugging in power tools that have the switch on invites accidents.
- d) **Remove any adjusting keys or wrench before turning the power tool on.** A wrench or a key that is left attached to a rotating part of the power tool may result in personal injury.
- e) **Do not overreach. Keep proper footing and balance at all times.** This enables better control of the power tool in unexpected situations.
- f) **Dress properly. Do not wear loose clothing or jewellery. Keep your hair, clothing, and gloves away from moving parts.** Loose clothes, jewellery, or long hair can be caught in moving parts
- g) **If devices are provided for the connection of dust extraction and collection facilities, ensure these are connected and properly used.** Use of these devices can reduce dust related hazards.

**4) Power tool Use and Care**

- a) **Do not force the power tool. Use the correct power tool for your application.** The correct power tool will do the job better and safer at the rate for which it was designed.
- b) **Do not use power tool if switch does not turn it on or off.** Any power tool that cannot be controlled with the switch is dangerous and must be repaired.
- c) **Disconnect the plug from the power source before making any adjustments, changing accessories, or storing the power tools.** Such preventive safety measures reduce the risk of starting the power tool accidentally.
- d) **Store idle power tools out of reach of children and do not allow persons unfamiliar with the power tool or these instructions to operate the power tool.** Power tools are dangerous in the hands of untrained users.
- e) **Maintain power tools. Check for misalignment or binding of moving parts, breakage of parts and any other condition that may affect the power tools operation. If damaged, have the power tool repaired before use.** Many accidents are caused by poorly maintained power tools.
- f) **Keep cutting tools sharp and clean,** Properly maintained cutting tools with sharp cutting edges are less likely to bind and are easier to control.
- g) **Use the power tools, accessories and tool bits ect., in accordance with these instructions and in the manner intended for the particular type of power tool, taking into account the working conditions and the work to be performed.** Use of the power tool for operations different from intended could result in a hazardous situation.

**5) SERVICE**

- a) **Have your power tool serviced by qualified repair person using only identical replacement parts,** This will ensure that the safety of the power tool is maintained.

**Additional information shall be provide**

- a) Instruction for putting into use
  - 1. Setting-up or fixing power tool in a stable position as appropriate for power tools which can be mounted on a support.
  - 2. Assembly
  - 3. Connection to power supply, cabling, fusing, socket type and earthing requirements.
  - 4. Illustrated description of functions.
  - 5. Limitations on ambient conditions.
  - 6. List of contents.
- b) Operating Instructions.
  - 1. Setting and testing.
  - 2. Tool changing.
  - 3. Clamping of work.
  - 4. Limits on size of work piece.
  - 5. General instructions for use.
- c) Maintenance and servicing.
  - 1. Regular cleaning, maintenance, and lubrication.
  - 2. Servicing by manufacture or agent, list of addresses.
  - 3. List of user-replaceable parts.
  - 4. Special tools which may be required.

## 2. Operations Cautions

- 1) Whenever changing a bit, make certain the Power Switch is in the “ OFF “ position and tool is unplugged.
- 2) Do not allow chemicals such as acetone, benzene, thinner, trichloroethylene ketone, or other similar chemicals to come in contact with the screwdriver housing as damage will result.
- 3) Do not drop or abuse the screwdriver.
- 4) Do not adjust the torque setting higher than 8 on the torque scale.
- 5) There should be a tool rest interval when cycles three seconds or longer. This tool is intended for a duty cycle of 0.8 sec on, 2.4 sec off.
- 6) Do not use this screwdriver for tightening wood screws. This is “ Metal Assembly Screw Driver ”
- 7) Do not operate the Forward / Reverse Switch the motor is running.
- 8) Whenever a tool is not being used, move the Power Switch to the “OFF” position and unplug the screwdriver.

### **CAUTION**

- Do not drop or abuse the tool.
- Whenever a tool is not being used, position the Power Switch to the “OFF” position and unplug the power cord.

### 3. Specifications

MODEL		BSD-1000	BSD-1200
Input voltage(DC)		32VDC	
Rated input		48W	
Bit torque	Kgf.cm	0.5-7	2-15
	Lbf.in	0.44-6.10	1.68-13.01
	N.m	0.05-0.69	0.19-1.47
Torque Adjustment		Stepless	
Unloaded Rotation Speed (R.p.m) ±10%		1000	1000
Metal assembly screw	Machine screw(mm)	1.4-2.6	2.0-4.0
	Tapping screw(mm)	1.4-2.0	2.0-3.0
Weight (g)		480	
Length (mm)		230	
Model of Torque Fixing Ring		KC-3	
Model of Suspension Rack		KH-4(KC&KH-2)	
Power controller		BSD-32P	
Bit Type		Ø4mm ,Ø5mm	

\* 1N.m=10.2Kgf.cm 1N.m=8.85Lbf.in



## 4. Description of Operation

Attaching / detaching bit and bit type


Push up the holder clamp by finger tip, and it will be unlocked. Thus, the bit can be freely attached and detached (single finger notion type) select such a bit whose shank is equal to the size shown below.

- Insert the power plug into a receptacle and set the changeover switch to “F” position.
- Apply the bit to the screw head and press the lever or push main body to, then the switch will be turned ON to start the motor running.
- When the screw is tighten and reach the torque that you had set, The tool will stopped automatically.
- To reset the tool by releasing the lever to the original position or releasing the bit From the screw head.
- To return the screw, set the changeover switch to “R” position.

## 5. Torque Adjustment Operation

To adjust the torque on these screwdrivers. Proceed as follows:

1. Determine the torque output of the tool by checking a tightened Fastener with a torque wrench.
2. Increase or decrease the torque by rotating the Spring Adjusting Ring. Rotating the Ring clockwise to a higher number on the torque Scale increase torque output while rotating the Ring counterclockwise to a lower number decreases the torque output.
3. Check the adjustment with a torque wrench. A number of factors will affect torque output from one job to another. Final torque adjustment should be made at the job through a of series of gradual increase. Always start below the desired torque and work upward.
4. Adjust the bit torque by changing the driving in length of the adjust ring at the end.
5. The relationship between torque scale and bit torque is as shown Ring, in the torque diagram. The figures of torque scale do not indicate bit torque values. However, the clamping torque of screw itself is different form type, size, material of the screw and the material of its mating part. Use it as standard to obtain an appropriate clamping torque.
6. The (Return torque method) in which once-clamped screw is returned with torque wrench or the like is available as one of torque control methods however, note that the measured values by the return torque method generally appear in 10%-30% lower than the actually clamping torque.
7. The torque checker measures the torque of screwdriver. The clamping torque of screw itself is different from the clamped conditions. Understand the correlation between clamping torque values and the torque checker values perform the torque control properly.



**CAUTION**

1. Also in reverse rotation, the clutch is turned off in such manner as in normal rotation, stopping the motor running. Accordingly, when the screw tightened at a large torque, set it to a higher torque scale.
2. The number from zero to eight on the Torque Scale are reference number only and not an indication of actual torque output.

**6. Accessories**

1. BIT Type :           No. 00 . . . . Bit use in dia 1.3-1.8mm screw  
                               No. 0 . . . . . Bit use in dia 1.6-2.0mm screw  
                               No. 1 . . . . . Bit use in dia 2.0-2.6mm screw  
                               No. 2 . . . . . Bit use in dia 3.0-4.0mm screw

BSD-1000	with BIT	1# & 2#	1 Pce. Each
BSD-1200	with BIT	1# & 2#	1 Pce. Each

2. Suspension rack and Torque fixing ring acceptable for use with the tool are available from KILEWS catalogue.

## **7. Servicing**

### **Maintenance and Inspection:**

1. The screw driver must be operated in top condition. one day working hour must be not more than eight hours.
2. Periodically check for wear of motor carbon brush, one day for eight hours use is normal, replace it after every five to six months.
3. Please note don't let the motor get over heated, every minute use 10-15 screws to operate.
4. The frequency use of this electric screw driver is over than eight hours a day, still it needs periodically testing and treatment. Every 5-6 months.
5. Inspect tool cords periodically and if damaged, have them repaired by an authorized service facility. Inspect extension cords periodically and replace if damaged.
6. Do not remove any labels. Replace any damaged label.


### **CAUTION**

1. The use of other than genuine KILEWS replacement parts may Result in decreased tool performance and increased maintenance, and may invalidate all warranties.
2. All repairs and maintenance of this tool and its word must be performed by an authorized service center.
3. KILEWS is not responsible for customer modification of tools for applications on which KILEWS was not consulted.
4. Repairs should by made only by authorized, trained personnel. Consult your nearest KILEWS authorized service center.
5. It is the responsibility of the employer to place the information in this manual into the hands of the operator.

**DO NOT ATTEMPT TO REPAIR THIS  
ELECTRIC SCREW DRIVER**

### **CAUTION**


**SAVE THESE INSTRUCTIONS  
DO NOT DESTROY**



**MODEL :**  
***BSD-1000LA/B/C/AD***  
***BSD-1200LA/B/C/AD***

CUSTOMER	DWG NAME	PRODUCTION NO.		
ITEM NO:	DWG NO:			
TITLE:	MATERIAL	SHRINK	THIRD ANGLE PROJECTION	
	DES. BY	DATE	UNIT	SCALE
	CHKD. BY	DATE		SHT NO.
	APPD. BY	DATE		OF SHTS.


NO	PARTS NO	PARTS NAME-E	Q'ty	NO	PARTS NO	PARTS NAME-E	Q'ty
1	AA50001-2	CORD	1	27	GG20271	GEAR SEAT	2
2	CJ20011	SUSPENSION RING	1	28	G20101	GEAR OF CENTER	1
3	CB15021	HOUSING-UNDERSIDE	1	29	GA30311-5	GEAR CASE	1
4	CA15101	HOUSING-UPSIDE	1	30	GN30321	MAIN BEARING	1
5	CC20031-3	TRIGGER	1	31	GC20301	CAM	1
6	CK2831-1	TRIGGER SPRING	1	32	GP30351	STEEL BALL-4MM	2
7	HB50073	START SWITCH	1	33	GD30381A	SHAFT A-TYPE	1
8	HA20091-4	CHANGEOVER SWITCH	1		GD20321-3	SHAFT B-TYPE	1
9	CI30212	SWITCH CAP FOR 1000	1		GD20321-2	SHAFT C-TYPE	1
	CI30211	SWITCH CAP FOR 1200	1		GD20321	SHAFT AD-TYPE	1
10	CH20102	SCREW	3	34	GP20331	STEEL BALLS FOR "A&AD" TYPE	2
11	MO15121-1	MOTOR ASSEMBLY	1		GP21291B	STEEL BALLS FOR "B&C" TYPE	2
12	EB33610-2	CERAMICS CAPACITOR	1	35	GF20341	WARRING PLATE FOR A,C,AD TYPE	1
13	EF51431	CAPACITOR	1		GF20341B	WARRING PLATE FOR B TYPE	1
14	MD20151	BRUSH CAP	2	36	GE20351-1	WARRING SPRING FOR 1000L	1
15	MC71411-1	CARBON BRUSH	2		GE20351	WARRING SPRING FOR 1200L	1
16	M10308	MOTOR TOP COVER	1	37	GY30421	WARRING SPRING BASE FOR A,C,AD	1
17	ME20181	ARMATURE BEARING	2		GY30421B	WARRING SPRING BASE FOR B TYPE	1
18	MH15191	ARMATURE	1	38	GK20231B	C-RING FOR B TYPE	1
19	MJ15631-1	MOTOR YOKE ASSEMBLY	1	39	GB30441-10	CLUTCH CASE FOR A,C,AD TYPE	1
20	MB20221	MOTOR END COVER	1		GB30441-7A	CLUTCH CASE FOR B TYPE	1
21	MA20211B	ASSEMBLING SPRING	2	40	GO30452	BIT SPRING FOR A,C,AD TYPE	1
22	MK20131-1	FUN	1		GO20391B	BIT SPRING FOR B TYPE	1
23	GZ22141-1A	CLUTCH ASSY 1000LA	1	41	GJ30461	BIT SLEEVE FOR A,C,AD TYPE	1
	GZ22141-1B	CLUTCH ASSY 1000LB	1		GJ3046B	BIT SLEEVE FOR B TYPE	1
	GZ22141-1C	CLUTCH ASSY 1000LC	1	42	GQ30471	"C" RING FOR A,C,AD TYPE	1
	GZ22141-1AD	CLUTCH ASSY 1000LAD	1		GQ21361	"C" RING FOR B TYPE	1
	GZ22141-2A	CLUTCH ASSY 1200LA	1	43	GL30481-5	TORQUE ADJ PINS	4
	GZ22141-2B	CLUTCH ASSY 1200LB	1	44	GM20431-1	TORQUE ADJ RING	1
	GZ22141-2C	CLUTCH ASSY 1200LC	1	45	GS30501	"C" RING FOR GM21381	1
	GZ22141-2AD	CLUTCH ASSY 1200LAD	1	46	GN30435	MAIN BEARING	1
24	GK20231	"C" RING	1	47	CD20111	COUPLER	1
25	GI20251-1	IRON WASHER	1	48	ML50571-2	MOTOR TOP COVER ASSEMBLY	1
26	GH20241	GEAR PLANET	8				



**MODEL :**  
**BSD-1000LD**  
**BSD-1200LD**

CUSTOMER	DWG NAME	PRODUCTION NO.		
ITEM NO:	DWG NO:			
TITLE:	MATERIAL	SHRINK	THIRD ANGLE PROJECTION.	
	DES. BY	DATE	UNIT	SCALE
	CHKD. BY	DATE		SHT NO.
	APPD. BY	DATE		OF SHTS.

NO	PARTS NO	PARTS NAME-E	Q'ty	NO	PARTS NO	PARTS NAME-E	Q'ty
1	AA50001-2	CORD	1	24	GK20231	"C" RING	1
2	CJ20011	SUSPENSION RING	1	25	GI20251-1	IRON WASHER	1
3	CB15021	HOUSING-UNDERSIDE	1	26	GH20241	GEAR PLANET	8
4	CA15101	HOUSING-UPSIDE	1	27	GG20271	GEAR SEAT	1
5	CC20031-3	TRIGGER	1	28	GG20261	GEAR SEAT	1
6	CK28031-1	TRIGGER SPRING	1	29	GA30311-5	GEAR CASE	1
7	HB50073	START SWITCH	1	30	GN30321	MAIN BEARING	1
8	HA20091-4	CHANGEOVER SWITCH	1	31	GC20301	CAM	1
9	CI30212	SWITCH CAP FOR 1000	1	32	GP30351	STEEL BALL-4MM	2
	CI30211	SWITCH CAP FOR 1200	1	33	GD20321-1	SHAFT D-TYPE	1
10	CH20102	SCREW	3	34	GP20331	STEEL BALLS FOR "D" TYPE	2
11	MO15121-1	MOTOR ASSEMBLY	1	35	GF20341	WARRING PLATE FOR D TYPE	1
12	EB33610-2	CERAMICS CAPACITOR	1	36	GE20351-1	WARRING SPRING FOR 1000L	1
13	EF51431	CAPACITOR	1		GE20351	WARRING SPRING FOR 1200L	1
14	MD20151	BRUSH CAP	2	37	GY30421	WARRING SPRING BASE FOR D	1
15	MC71411-1	CARBON BRUSH	2	38	GB30441-10	CLUTCH CASE FOR D TYPE	1
16	M10308	MOTOR TOP COVER	1	39	GO30452	BIT SPRING FOR D TYPE	1
17	ME20181	ARMATURE BEARING	2	40	GJ30461	BIT SLEEVE FOR D TYPE	1
18	MH15191	ARMATURE	1	41	GQ30471	"C" RING FOR D TYPE	1
19	MJ15631-1	MOTOR YOKE ASSEMBLY	1	42	GL30481-5	TORQUE ADJ PINS	4
20	MB20221	MOTOR END COVER	1	43	GM20431-1	TORQUE ADJ RING	1
21	MA20211B	ASSEMBLING SPRING	2	44	GS30501	"C" RING FOR GM21381	1
22	MK20131-1	FUN	1	45	GN30435	MAIN BEARING	1
23	GZ22141-1D	CLUTCH ASSY 1000LD	1	46	CD20111	COUPLER	1
	GZ22141-2D	CLUTCH ASSY 1200LD	1	47	ML50571-2	MOTOR TOP COVER ASSEMBLY	1

**BSD****BSD-32P**

No.	PARTS No.	PARTS NAME.	Q.TY
1	P11013	HOUSING 32V 40W FOR BSD-32P	1
2	EG50101-22K	PCB POWER SUPPLY FOR BSD-32P	1
3	A10105-3	CORD 2C× 1.5m	1